

PETROLEUM COMPANY OF TRINIDAD AND TOBAGO LIMITED

Administration Building, Pointe-à-Pierre, Trinidad, West Indies Telephone: (868) 658-4200/10/20/30. Telefax: (868) 658-1236

MEDIA RELEASE

Response Efforts Ongoing

Petrotrin is currently responding to a leaking subsea clamp on Well S-694 located in the Soldado North Field which was observed on Monday (2018 April 30). The leak has been confined to the immediate vicinity of the facility and is being managed by response personnel on site.

The Company's Operations and Health, Safety and Environment (HSE) personnel immediately responded and Petrotrin's Incident Command System (ICS) was activated.

Aerial, marine and land surveillance exercises conducted since the initial report of the oil leak have revealed no observable impact on any of the shorelines along the south western peninsula.

The Ministry of Energy & Energy Industries, the Environmental Management Authority (EMA) and the other regulatory authorities have been notified of the incident.

Corporate Communications Department 2018 May 02